


## Control Package

N.C. DAMPER		DAMPER ACTUA 5-10 PSI SPRING RANGE MCP-8031		FACTORY PIPING FIELD PIPING
Job:		Tag:		BPS Bypass Terminal Direct Acting Normally Closed Pressure Dependent
Location:		Submitted by:		
Architect:				
Contractor:		SD-1601	10/11/2006	Pressure Dependent
Contractor.		OD-1001	10/11/2000	



## Control Package



## SEQUENCE OF OPERATION

## 1.) COOLING ONLY

Discharge air flow is at zero when thermostat branch pressure is below 5 PSIG. On a rise is room temperature the thermostat branch pressure increases to 10 PSIG and air flow increases to maximum.

2.) Damper fails closed with loss of pneumaticd air.

Job:	Tag:		DDC Dynasa Tarminal
Location:	Submitted by:		BPS Bypass Terminal Direct Acting
Architect:	Submitted by.		Normally Closed
Engineer:			Pressure Dependent
Contractor:	SD-1601P2	10/11/2006	